


Project History

Exterior Masonry Restoration & Curtain wall Repair

July 1999 – February 2011

Waterway Tower

433 E. Las Cominas
Irving, Texas



Project Work Description

- Replace all masonry joints – 100% tuck-pointing
- Replace all exterior sealants
- New metal over-cladding of all exterior window frames
- Replace all shelf angle flashing behind brick facade