

Project Information

Project Name: **Albuquerque Federal Building** No.: **1028**
Address: **421 Gold Avenue, Albuquerque, NM** Start Date: **February 14, 2011**
Supervisor(s): **Nick Calhoun** Completion Date: **December 14, 2011**

General Satisfaction

Not Satisfied Satisfied Very Satisfied

Check All That Apply in relevance to Frontier Waterproofing's Work and their Employees

High Quality Work Knowledgeable Employees Respectful Employees
 Quick Responses Safe Environment Excellent Motivation & Character
 Other: _____

Details

Was the project completed in a timely manner?

yes

What is your general opinion about the on-site supervisor? Was he professional and knowledgeable?

If all the supervisory staff that I work with had half the customer relations skills and professionalism as Nick Calhoun my job would be too easy.

Was the work done in accordance to the specs?

yes

Were there any issues that arose during this project that pertained to Frontier Waterproofing, Inc.?

Yes, the normal complaints from tenants. Nick Calhoun responded in the most professional manner and resolved all issues beyond my expectations.

Would you consider working with Frontier Waterproofing, Inc. again in the future?

YES

Other Comments, Questions, or Concerns:

I have never had a smoother project of this scale.

Paul Abernathy

Signature of Representative at GSA

1/3/2012

Date